


# Run Out Validation Flow Chart



**\*To assure the drum is mounted properly:**

- Mount the drum, mark the high and low spot on the drum as shown by the dial indicator.
- Rotate the drum 180° relative to the mounting fixtures.
- Measure the high and low spots again. If they match the location of the previous ones, the drum is mounted correctly. If not, check the mounting hardware for burrs, nicks etc.

